

1/7




FIG. 1

2/7






FIG. 2

3/7


1. starting point




2. Introducing Edge-Edge association




3. test whether EE possible



4. Determine transformation matrix



5. Apply transformation



6. Reduce degree of freedom





FIG. 3

417




Fig 4




Fig 5

09747678-426280

5/7




Fig 6




Fig 7

0344959-42260



7/7




Fig 10




Fig 11